

L Number	Hits	Search Text	DB	Time stamp
1	2	"6284085" and acid	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 17:37
2	8	"6284085"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:08
3	1102	rca near2 clean\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:08
4	36820	65/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:08
5	1	(rca near2 clean\$4) and 65/\$.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:09
6	76	(rca near2 clean\$4) near5 acid	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:14
7	2	(rca near2 clean\$4) near3 defin\$6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:11
8	19	nitric adj acid same (rca near2 clean\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:35
9	235	65/407.cccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:35
10	618609	softening or melting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:36
11	77	65/407.cccls. and (softening or melting)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/28 18:43
12	72	65/407.cccls. not (65/407.cccls. and (softening or melting))	USPAT	2004/05/28 18:49
13	1664	fusing adj temperature	USPAT	2004/05/28 18:49
14	11	(fusing adj temperature) near4 (lower or higher) and 65/\$.cccls.	USPAT	2004/05/28 18:54
15	0	(bond\$3 adj (point or temperature)) near4 (lower or higher) and 65/\$.cccls.	USPAT	2004/05/28 18:55
16	7	(bond\$3 adj (point or temperature)) near4 (lower or higher) and 65/\$.cccls.	USPAT	2004/05/28 18:56

17	348	(soft\$8 adj (point or temperature)) near4 (lower or higher) and 65/\$.ccis.	USPAT	2004/05/28 18:56
18	158	(soft\$8 adj (point or temperature)) near4 (lower or higher) and 65/4\$.ccis.	USPAT	2004/05/28 18:57
19	54	(soft\$8 adj (point or temperature)) near4 (lower or higher) and 65/40\$.ccis.	USPAT	2004/05/28 19:05
20	156	65/41	USPAT	2004/05/28 19:05
21	14230	bond\$3 near2 (temperature or point)	USPAT	2004/05/28 19:06
22	11	(bond\$3 near2 (temperature or point)) and 65/41	USPAT	2004/05/28 19:08
23	14230	(bond\$3 near2 (temperature or point))	USPAT	2004/05/28 19:08
24	191410	(melt\$3 near2 (temperature or point))	USPAT	2004/05/28 19:08
25	42688	(soft\$7 near2 (temperature or point))	USPAT	2004/05/28 19:09
26	1958	((bond\$3 near2 (temperature or point))) and ((soft\$7 near2 (temperature or point)))	USPAT	2004/05/28 19:09
27	62	65/\$.ccis. and (((bond\$3 near2 (temperature or point))) and ((soft\$7 near2 (temperature or point))))	USPAT	2004/05/28 19:11
28	1958	((bond\$3 near2 (temperature or point))) and ((soft\$7 near2 (temperature or point)))	USPAT	2004/05/28 19:11
29	619	((bond\$3 near2 (temperature or point))) same ((soft\$7 near2 (temperature or point)))	USPAT	2004/05/28 19:11
30	24	65/\$.ccis. and (((bond\$3 near2 (temperature or point))) same ((soft\$7 near2 (temperature or point))))	USPAT	2004/05/28 19:12